



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Pete Hess Environmental Scientist III	•			
Company	Dan Guy	-			

Inspection Report

Permit Number:	C0070022
Inspection Type:	PARTIAL
Inspection Date:	Thursday, November 19, 2009
Start Date/Time:	11/19/2009 9:30:00 AM
End Date/Time:	11/19/2009 10:40:00 AM
Last Inspection:	Wednesday, October 28, 2009

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear, 40's F.

InspectionID Report Number: 2190

Accepted by: jhelfric

12/7/2009

Permitee: SAVAGE SERVICES CORP Operator: SAVAGE SERVICES CORP

Site: SAVAGE COAL TERMINAL

Address: 6340 S 3000 E STE 600, SALT LAKE CITY UT 84121

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

153.46	Total Permitted
132.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

Types of Operations Federal ✓ Underground State ✓ Surface ✓ Loadout County Processing Fee Other □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the quarterly electronic submittal of surface and ground water monitoring information.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46 Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov **Date**

Monday, November 23, 2009

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Thursday, November 19, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations	V		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		V		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading		✓		
13.	Revegetation				
14.	Subsidence Control		V		
15.	Cessation of Operations		V		
16.a	a Roads: Construction, Maintenance, Surfacing	V			
16.Ł	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓		✓	
18.	Support Facilities, Utility Installations	V			
19.	AVS Check				
20.	Air Quality Permit	V		V	
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Thursday, November 19, 2009

Page 3 of 3

3. Topsoil

The Permittee, through Blackhawk Engineering Company, in consultation with Mt. Nebo Scientific, submitted an application for DOGM approval of a temporary seed mix in an effort to establish a vegetative protective cover on the topsoil and subsoil piles located adjacent to the four fine coal settling basins. The Division has identified this permitting application as Task ID # 3421 for tracking purposes. An expedited approval has been requested by this inspector, in order that the Permittee can accomplish re-seeding during current soil moisture conditions. Representatives of the DOGM technical staff visited the site on November 23, 2009 to evaluate the stockpiled soils as part of their review process. It has been recommended that the four new species possibly be included as a supplement to the already approved temporary seed mix. A final determination of this application remains pending.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee has completed the cleanout of fine coal settling basin #3, and is in process of cleaning #4. Mr. Guy intends to recertify these basins the week of November 23, 2009. Sediment pond #1 needed to be pumped to provide sufficient sediment and runoff capacity for the design event. Pond #1 also receives wash down and process water from the wash plant. The pond #1 volume is pumped into pond #6. Ponds #2 and #3, (which operate in series with #1) were dry. The Permittee initiated pumping of #1 during today's inspection. There were no other issues identified.

4.e Hydrologic Balance: Effluent Limitations

No discharge was observed at the pond #001 open channel spillway.

7. Coal Mine Waste, Refuse Piles, Impoundments

Loading and shipping of the material in the coal waste pile continues.

17. Other Transportation Facilities

An Intermountain Power Agency train was being loaded during today's inspection.

20. Air Quality Permit

The Permittee waters operational roads when ambient air temperatures allow.